


IN1128 VALVE INTERRUPTER



Notes:

1. Make sure all connections are tight.
2. 10730 Control must be in mode two, this is indicated by the repeating double blue flash after control has fully booted up.
3. Make sure 99055 Label is placed so that the bottom terminal block screws are still visible, do not over them with the label. Also the blue Sensor Open should be closest to the outside end of the control assembly.
4. After connectors are attached they should be firmly plugged into the 10730 controller.

NOTE: To change modes disconnect power, then connect DIR 1, DIR 2, and COM together. With the wires connected reconnect power. Once the LED flashes blue disconnect the wires. This will cycle through the modes.